



basic machine

guide wheel

carbide inserts

additional clamping screws

optional accessory guide disc


①	basic machine	type	order-number	minimum order quantity
	basic machine (230V / 7.900rpm)	SMA 30-EF/24.1-45/R	0101.360.15-00003	1
	basic machine (110V / 7.900rpm)	SMA 30-EF/14.1-45/R	0101.360.15-00004	1
	basic machine (230V / 2.500-7.900rpm)	SMA 30-EFR/24.1-45/R	0101.380.16-00001	1
	basic machine (110V / 2.500-7.900rpm)	SMA 30-EFR/14.1-45/R	0101.380.16-00002	1

i basic machines are equipped with case, tools for changing carbide inserts, operating manual; with 45°-milling head, without guide wheel/disc and carbide inserts

②	guide wheel for			type	order-number	minimum order quantity	
	bevel	KX	up to 9mm	∅ 26,30	DS1-45-I3KX.1	0101.363.15-00001	1
	radius + bevel	KXR + KX	2,5mm up to 5mm	∅ 28,80	DS1-R2-I3KX.1	0101.363.15-00002	1
	radius + bevel		3mm up to 6mm	∅ 28,55	DS1-R3-I3KX.1	0101.363.15-00003	1
	radius + bevel		4mm up to 7mm	∅ 27,55	DS1-R4-I3KX.1	0101.363.15-00004	1

③	carbide inserts for			type	order-number	minimum order quantity	
	bevel	KX	up to 9mm	B02	KX-B02-A1.1	0101.404.13-00006	10
	radius	KXR	2,5mm	B02	KXR2.5-B02-A1.1	0101.404.14-00005	10
	radius		3mm	B02	KXR3-B02-A1.1	0101.404.13-00004	10
	radius		4mm	B02	KXR4-B02-A1.1	0101.404.13-00005	10

i B02 für Stahl und NE-Metalle (universal)
other coatings on request

④	clamping screw	type	order-number	minimum order quantity
	pack of 10	CS 30-11-P10	0101.203.09-00015	1

⑤	guide disc for			type	order-number	minimum order quantity	
	bevel	KX	up to 9mm	∅ 26,30	GD1-AB45/∅26.30-I3KX.2	0101.363.16-00003	1
	radius + bevel	KXR + KX	2,5mm up to 5mm	∅ 28,80	GD1-R2/∅28.80-I3KX.2	0101.363.16-00004	1
	radius + bevel		3mm up to 6mm	∅ 28,55	GD1-R3/∅28.55-I3KX.2	0101.363.16-00005	1
	radius + bevel		4mm up to 7mm	∅ 27,55	GD1-R4/∅27.55-I3KX.2	0101.363.16-00006	1

Ⓐ	machine-set	type	order-number	minimum order quantity
	45° / radius 3mm / 230V / 7.900rpm	SMA 30-EF/24.1-45/R3	0101.360.15-00002	1
	45° / radius 3mm / 110V / 7.900rpm	SMA 30-EF/14.1-45/R3	0101.360.16-00001	1
	45° / radius 3mm / 230V / 2.500-7.900rpm	SMA 30-EFR/24.1-45/R3	0101.380.15-00001	1
	45° / radius 3mm / 110V / 2.500-7.900rpm	SMA 30-EFR/14.1-45/R3	0101.380.16-00003	1

i machines are equipped with tool (for changing carbide inserts), operating manual, milling body, guide wheel and carbide inserts as follows:

1x beveling machine SMA 30-EF/24/14.1 or SMA 30-EFR/24/14.1 with 45°-milling body incl. 3 clamping screws CS 30-11

1x guide wheel DS1-R3-I3KX.1 / ∅ 28,55 for bevels up to 6mm and radius R = 3mm

3x bevel-carbide insert KX-B02-A1.1

3x radius-carbide insert KXR3-B02-A1.1

3x clamping screw CS 30-11

1x copper paste

1x hexagon screwdriver SW5

1x torx wrench T15