



①	basic machine	type	order-number	minimum order quantity
	beveling machine	SMA 20-PF/25.1-45/R	0109.110.16-00003	1



machines are equipped with tool (for changing carbide inserts), operating manual and 45°-milling head, without guide wheel, without carbide inserts

②	guide wheel for		type	order-number	minimum order quantity	
	bevel	up to 3,5mm	∅ 24,40	DS1-AB45/∅24,40-I3SX.1	0101.113.16-00015	1
	bevel	up to 7,0mm	∅ 19,40	DS1-AB45/∅19,40-I3SX.1	0101.113.16-00016	1
	radius + bevel	1,2mm up to 2mm	∅ 26,10	DS2-AB45/R1.2/∅26.10-I3SX.1(L)	0101.113.17-00016	1
	radius + bevel	1,2mm up to 6,5mm	∅ 19,80	DS2-AB45/R1.2/∅19,80-I3SX.1(S)	0101.113.17-00015	1
	radius + bevel	2,5mm up to 5mm	∅ 21,69	DS2-AB45/R2.5/∅21,69-I3SX.1	0101.113.17-00014	1

③	carbide insert for		type	order-number	minimum order quantity	
	bevel	up to 7mm	B02	SX-B02-A1.1	0101.404.15-00002	1
	radius	1,2mm	B02	SXR1.2-B02-A1.1	0101.404.16-00012	1
	radius	2,5mm	B02	SXR2.5-B02-A1.1	0101.404.15-00001	1



B02 for steel and non-ferrous metals (universal)

packing unit = 10 pcs

④	clamping screw	type	order-number	minimum order quantity
	pack of 10	CS 30-09-P10	0101.203.16-00001	1

Ⓐ	machine-set	type	order-number	minimum order quantity
	machine-set 45°+R=2,5mm	SMA 20-PF/25.1-45/R2.5	0109.110.17-00001	1



machines are equipped with tool (for changing carbide inserts), operating manual, milling body, guide wheel and carbide inserts as follows:

- 1x beveling machine SMA 20-PF/25.1 with 45°-milling body incl. 3 clamping screws CS 30-09
- 1x guide wheel DS2-AB45/R2.5/∅21,69-I3SX.1 for beveling up to 5mm and radius R = 2,5mm
- 3x bevel-carbide inserts SX-B02-A1.1
- 3x radius-carbide inserts SXR2.5-B02-A1.1
- 3x clamping screws CS 30-09
- 1x copper paste
- 1x torx wrench T15