


WA-5000 MOTOR ASSEMBLY AND PARTS LIST



The part numbers with () are included in the Ass'y parts written above them.

No.	Part No.	Part Name	Q'ty	Price
201	TQ06824	Cord Protector (Strain Relief)	1	
202	TQ06843	Connecting Cable (Motor Cord)	1	
203	TQ06819	Self Tapping Screw HC 4.8 X 38	4	
204	TQ06818	Cap for Drill Motor Housing	1	
205	TQ06850	Motor Housing	1	
206	TB05193	Brush Holder Ass'y (no brushes)	2 sets	
207	(TB05187)	Carbon Brush Ass'y (2 pcs/set)	1 set	
208	TQ06838	Contact Washer	1	
209	TQ06828	Screw ZM 4 X 12	2	
210	TQ06820	Spring Washer B4	2	
211	TQ06851	Condenser	1	
212	TB07200	Stator Ass'y (115V)	1	
	TB07201	Stator Ass'y (230V)	1	
213	TQ06852	Insulated Tubing	1	
214	TQ06849	Self Tapping Screw HC4.8 X 60	2	
215	TQ06848	Air Guiding Ring (Fan Shroud)	1	
216	TQ06839	O Ring 22 X 2.5	1	
217	TP00468	Ball Bearing 608ZZ	2	
218	TB07202	Armature Ass'y (115V)	1 set	
219	TP01036	Retaining Ring C-28	1	
220	TP00498	Ball Bearing 6001ZZ	1	

No.	Part No.	Part Name	Q'ty	Price
221	TP06390	Retaining Ring C-11	1	
222	TB05479	Bearing Bracket Ass'y	1 set	
223	TQ10648	Caution - Change Label	1	
224	TQ07076	Gear Block 34/40Z	1	
225	TQ07075	Pinion Shaft 13Z	1	
226	TQ07077	Key A5 X 5 X 28	1	
227	TQ06825	Grease Chamber	1	
228	TQ07069	Intermediate Gear 34Z	1	
229	TQ07070	Pinion Shaft 11/17Z	1	
230	CP04989	External Retaining Ring C15	1	
231	TQ07073	Spindle Gear 45Z	1	
232	TQ07074	Fitting Washer 15 X 22 X 0.2	1	
233	TQ06830	Ball Bearing 6203LLU	2	
234	TB05399	Coupling Bolt Ass'y	1 set	
235	TQ06642	Notched Pin 4 X 12	1	
236	TQ06844	Gear Case Seal	1	
237	TB05478	Gear Case Ass'y	1 set	
238	TB03598	Gear Changer Ass'y	1 set	
239	TQ10647	Change Knob Label	1	
240	TQ06840	Self Tapping Screw HC2.9 X 9.5	4	
241	TQ07072	Key A5 X 5 X 12	1	
242	TQ07071	Spindle	1	